TA30721_Apple_Internet_Router_3-0_GeoPort_Compatibility_(1293)_(TIL14119).pdf

Apple Internet Router 3.0: GeoPort Compatibility (12/93)

When I use Apple Internet Router (AIR) 3.0 on my Quadra 840AV, the router runs properly. If Express Modem for Geoport is loaded, the 840AV crashes at bootup.

Are the Apple Internet Router 3.0 and the GeoPort software compatibile?

This article has been archived and is no longer updated by Apple. The Centris/Quadra AV computers require Apple Internet Router 3.0.1 when the Express Modem for GeoPort software is installed. AIR 3.0 will either crash at boot (if the router auto-starts at boot) or will crash with a "Type 3" error (if the router is manually started), when the GeoPort software has been installed on the system also.

Published Date: Feb 19, 2012